

FSM keyboard shortcuts



Shortcut key	Function
Alt-A	Attenuator
Alt-B	Antenna gain / factor
Alt-L	Loss
Alt-R	Rx noise figure
Alt-Y	Frequency
Ctl-D	Sound card control - record
Ctl-E	Send text file
Ctl-I	Import antenna calibration file
Ctl-K	Sound card control - playback
Ctl-M	Calibrate receive
Ctl-P	Play wave samples
Ctl-R	Record TSV file
Ctl-S	Save text file
Ctl-T	Transfer results
Ctl-U	Unload antenna calibration file
Ctl-W	Save wav file
Shift-F1	Measure - Step 1
Shift-F2	Measure - Step 2
Shift-F3	Measure - Step 3

FSM V1.0.13

FSM keyboard shortcuts



Function	Shortcut key
Antenna gain / factor	Alt-B
Attenuator	Alt-A
Calibrate receive	Ctl-M
Frequency	Alt-Y
Import antenna calibration file	Ctl-I
Loss	Alt-L
Measure - Step 1	Shift-F1
Measure - Step 2	Shift-F2
Measure - Step 3	Shift-F3
Play wave samples	Ctl-P
Record TSV file	Ctl-R
Rx noise figure	Alt-R
Save text file	Ctl-S
Save wav file	Ctl-W
Send text file	Ctl-E
Sound card control - playback	Ctl-K
Sound card control - record	Ctl-D
Transfer results	Ctl-T
Unload antenna calibration file	Ctl-U

FSM V1.0.13